

## ANEXA G

### Imagini Fotografice



1. Aspect al DJ 592 la iesirea din Timisoara spre Mosnita (km 5 + 200, Calea Buziasului, drum cu 4 benzi de circulatie)



2. DJ 592. Refulare de margine. Fisuri



3. DJ 592. Fisuri transversale



4. DJ 592. Fagase si refulari de margine



5. DJ 592. Scurgerea apelor deficitara



6. DJ 592. Scurgerea apelor deficitara